

Square Bracket for Base ▶ Simplified Type Through Hole Type/Threaded Hole Type Bolt Reverse Type Through Hole Type/Threaded Hole Type



Please order according to the diagram

①~② Select the type and parameters in the order for ordering.

■ Simplified Type

Model(①Code)

KWAAA

— ●DH7

D10

■ Bolt Reverse Type

Model(①Code)

KWACA

— ●DH7

D10



● Discounted Price
Quantity 1~9 10~
Price 100% Separate Quotation
Price Excluding Tax (Yen)

Mounting Parts
Bases - Post Clamps
31

■ Simplified Type

Simplified Type		Material		Surface Treatment	Accessory(Screws)
Through Hole Type	Threaded Hole Type	International	Equivalent		
KWAAA	KWABA	Q235	SS400	Black Oxide Finish	Hex Socket Head Cap Screw
KWAAB	KWABB			Electroless Nickel Plating	Hex Socket Head Cap Screw (Stainless Steel)

Through Hole Type

Threaded Hole Type

Model		A	B	C	f1	f2	G	b	b1	N	H	M	X	S	d	d1	Z	W
Code	DH7																	
Through Hole Type	10	+0.015	30			9				M4	9							
Threaded Hole Type	12	+0.018	32	20	6	10	11	4.5	8	M4	10	M4	4.75	9.5	4.5	8	5	
KWAAA	15	0	39			14				M5	12							
KWABA	20		48	28	27	17.5	16	6.6	11	M6	15	M6	7	13	6.6	11	7	2
KWAAB	25	+0.021	52	32	31	20	17			M6	17			17				
	30	0	63	40	39	22.5	20	8.5	14	M8	21	M8	9.5	20	8.5	14	9	

■ Bolt Reverse Type

Bolt Reverse Type		Material		Surface Treatment	Accessory(Screws)
Through Hole Type	Threaded Hole Type	International	Equivalent		
KWACA	KWADA	Q235	SS400	Black Oxide Finish	Hex Socket Head Cap Screw
KWACB	KWADB			Electroless Nickel Plating	Hex Socket Head Cap Screw (Stainless Steel)

Through Hole Type

Threaded Hole Type

Model		A	B	C	F	f1	f2	f3	G	b	b1	h	N	H	M	X	S	d	d1	Z	W
Code	DH7																				
Through Hole Type	10	+0.015	40		28	9	19						M4	9							
Threaded Hole Type	12	+0.018	42	20	30	10	20	6	11	4.5	8	4.6	M4	10	M4	4.75	9.5	4.5	8	5	
KWACA	15	0	50	22	38	14	24		12	5.5	9.2	5.5	M5	12	M5	5.5	10	5.5	9.5	6	2
KWACB	20		60	30	45	17.5	27.5	7.5	16	6.6	11	6.5	M6	15	M6	7	15	6.6	11	7	
	25	+0.021	65	35	50	20	30		20				M6	17			20				
Threaded Hole Type	30	0	80	45	60	22.5	37.5	10	25	8.5	14	9	M8	21	M8	9.5	25				
KWADA	35		85	50	65	25	40		30				M8	24			30	8.5	14	9	
KWADB	40	+0.025	100	60	75	30	45	12.5	35				M10	26	M10	12	35				3
	50	0	110	70	85	32.5	52.5		45	11	17.5	11	M10	33	M10	14.5	40	11	17.5	11	